



FAA FO4R187M
EASA 145.5081
23413 66th Ave. South
Kent WA 98032 USA
www.pacificaerotech.com
T 253.395.9535 F 253.395.9541



Work Order Disposition Report

Page : 1 of 2

Status : OVERHAULED	
Warranty Y/N :	
Contact :	Pacific Aero Tech, LLC.
Mechanic : SRT	23413 66th Ave. South
WH Code :	Kent, WA 98032 USA
Cust Charge :	Tel. : T 253.395.9535
Division :	Fax : F 253.395.9541
Reject Doc :	
A/C ID # :	
Confirmed Y/N :	
For Customer : Our Part	W/O Kind : [P2]

Cust P.O. : N/A	P/N : 5-89354-3149	Lot/Batch# :
Our Ref : AC PH2 REPAIR	Desc : #1 WINDSHIELD, LH	Tag Date : 10/18/2024
Your Ref :	S/N : 09034H8900	Life :
TSN/TSO :	MFG : PPG INDUSTRIES, INC	Manual : 56-11-11
Mfg Date :	Qty : 1	Cond As: OH
Completed P/N : 5-89354-3149	S/N As : 09034H8900	Revision : 57 / Nov-01-2023
		Into Bin Loc : [w/h]: PATO
Company : 1	Division : WIN	Department : 05
Order Date : Sep-04-2024	Received Date : Jun-19-2024	Due Date : Oct-17-2024
		Print Date : Oct-18-2024

WORK ORDER No. 147258

Preliminary Insp.

HEATER-40.42

SENSORS-306.16/306.10

Corrective Action

WINDOW WAS OVERHAULED, TESTED, AND INSPECTED IAW REPAIR SPECIFICATION

NO. PAT-AQRD-0245 REV H DATED 06-DEC-2021 AND MFG'S CMM CHAPTER 56.

Item	Part Number / Description	Part Status	Qty	Cond	Discrepancy / Disposition
PARTS & MATERIALS					
20	PRC1425 B 1/2	32 - Installed Component	2 EA	NE	Disc. : _____
	SEALANT - PR 1425 B-1/2, 6OZ SEMKIT				Disp. : _____
	MDL#: SEALANT				
21	PR1425B1-2	32 - Installed Component	2 EA	NE	Disc. : _____

Continued on next page...



FAA FO4R187M
EASA 145.5081
23413 66th Ave. South
Kent WA 98032 USA
www.pacificaerotech.com
T 253.395.9535 F 253.395.9541



Work Order Disposition Report

Page : 2 of 2

WORK ORDER No. 147258

22	SEALANT - PR 1425 B 6 OZ SEMKIT 654 (AVIALL)	32 - Installed Component	2 EA NE	Disp. : _____
	PRC1425 B 1/2			Disc. : _____
23	SEALANT - PR 1425 B-1/2, 6OZ SEMKIT	32 - Installed Component	1 EA NE	Disp. : _____
	MDL#: SEALANT			Disc. : _____
	PAT-5-89354-3039			Disp. : _____
	PRESSURE SEAL, LH			Disc. : _____
	MDL#: 737			

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 147258	
4. Organization Name and Address: Pacific Aero Tech, LLC. 23413 66th Ave. South Kent, WA 98032 USA		5. Work Order/Contract/Invoice Number: N/A			
6. Item: 7. Description:		8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	#1 WINDSHIELD, LH	5-89354-3149	1 EA	09034H8900	OVERHAULED
12. Remarks: Referencing manual No. 56-11-11 Revision: 57 Revision Date: NOV 01 2023 WINDOW WAS OVERHAULED, TESTED, AND INSPECTED IAW REPAIR SPECIFICATION NO. PAT-AQRD-0245 REV H DATED 06-DEC-2021 AND MFG'S CMM CHAPTER 56.					
Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA 145.5081".					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.					
14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12					
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14b. Authorized Signature:	
					
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14c. Approval/Certificate No.:	
				F04R187M	
				14c. Date (dd/mm/yyyy):	
				18/Oct/2024	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					