



FAA REPAIR STATION 68IR700B
EASA REFERENCE 145.6295
600 RADIATOR ROAD
INDIAN TRAIL, NC 28079
Ph: 704.821.4266 Fax:
Email: service@iconaerospace.com

Page 1

WORK ORDER

W249538

Date Released: 23/Aug/2024

TEARDOWN REPORT

GOAL AVIATION	Cust RO#: 650240005	Manuals		
	P/N: TD1702-1002	Loc	ATA	Revision
Rybí 116, 742 65	S/N: 16430	LC-001	38-30-01	5 06/Dec/2004
Contact: QUOTES	Desc: SWITCH, TOILET TIMER			
Contact Ph: 420 601 313 587				
Contact Fax:	Mfgr: LEACH CORP.			
Work Requested	UNIT RECEIVED FOR OVERHAUL AS PER O.E.M SPECS			

FINDINGS

RECEIVING INSPECTION:
VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.

PRELIMINARY INSPECTION:
FAILED

HIDDEN DAMAGE:
NONE

CONTINUED INSPECTION:
TESTED. UNIT FAILED FUNCTIONAL TEST. FOUND UNIT DIRTY. UNIT REQUIRES COVER TO BE REPAIRED. UNIT REQUIRES CLEANING AND PAINT. DISASSEMBLY IS REQUIRED.

CORRECTIVE ACTION: UNIT CONDITION OVERHAULED
REPAIRED CASE. CLEANED AND REASSEMBLED UNIT. TESTED AS PER O.E.M. SPEC'S. ALL WORK PERFORMED AS PER O.E.M SPEC'S.

SB'S, AD'S AND RMK'S:
NONE

CERTIFICATION

SERVICE PERFORMED: ☒ OVERHAULED

PARTS AND MATERIALS

QTY	PART NUMBER	SERIAL NUMBER	DESCRIPTION	COND
1	002-1831-001		CASE	RP


MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY:


MATTHEW S. JACKSON

DATE: 23/Aug/2024

1. Approving Civil Aviation Authority/Country FAA/United States		2.		3. Form Tracking Number: 650240005	
AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG					
4. Organization Name and Address: Icon Aerospace, LLC 600 RADIATOR ROAD INDIAN TRAIL, NC 28079				5. Work Order/Contract/Invoice Number: W249538	
6. Item		7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:
1	SWITCH, TOILET TIMER	TD1702-1002		1	16430
					OVERHAULED
12. Remarks: OVERHAULED in Accordance with LEACH CORP. CMM 38-30-01 Rev.:5 Date:06/Dec/2004					
FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W249538					
COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADs): N/A COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs): N/A					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.			14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature:		13c. Approval/Authorization No.:		14b. Authorized Signature: 	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed): MATTHEW S. JACKSON	
				14e. Date (dd/mm/yyyy): 23/Aug/2024	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					