

1. Approving Civil Aviation
Authority/Country:

2.

AUTHORIZED RELEASE CERTIFICATE

3. Form Tracking Number:

AV#: 116683

FAA/UNITED STATES

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

4. Organization Name and Address:

CSI AEROSPACE, INC.

2020 W. DETROIT
BROKEN ARROW, OK 74012

UNITED STATES
Ph: 918-258-4290, Fax: 918-258-4612

FAA Approval Holder: VZER333Y

5. Work Order/Contract/Invoice
Number:

RO #: 650250002

WO #: P46448

6. Item:

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1

PITOT TUBE

0851HT-1

1

224845

OVERHAULED

12. Remarks:

The work performed (see block 11) was accomplished IAW the noted / applicable CMM or other approved FAA data listed under Manual ID: The work order (see block 5) describing the work performed is on file at this repair station
Manual ID: CSI-9909, Revision #: E, Revision Date: 9/11/2023

CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART-145 AND IN RESPECT TO THAT WORK THE COMPONENT IS
CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART-145 APPROVAL NUMBER EASA-145.5180.

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No:

14b. Authorized Signature:

14c. Approval/Certificate No:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):
CHARLES BOWER

14e. Date (dd/mm/yyyy):
24/Jun/2025

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.
Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

To:
GOAL AVIATION LTD
KUNIN 30
KUNIN 74253
CZECH REPUBLIC

Ship To:
GOAL AVIATION LTD
KUNIN 30
KUNIN, 74253 CZECH REPUBLIC

Ref #: 650250002

PN:0851HT-1

Serial Numbers: 224845

Code: GA2

Descr: PITOT TUBE

Symptoms:

CUSTOMER REASON FOR REMOVAL/ RETURN

NOT REPORTED

Faults:

NOSE - EROSION

NOSE - DRAIN HOLE EROSION

TIP - EROSION

TIP - NICKS

Corrective Actions:

MAINTAINED IAW APPLICABLE STANDARD

PITOT TUBE OVERHAULED IAW CSI-9909 REPAIR SPECIFICATION, REV E, DATED 11/SEP/2023.

PN	Description
9909P300-1	9909 NOSE ASSEMBLY
9909P102-1	9909 PITOT LINE
99-EC-005	TERMINAL CONNECTOR 1/4 X 750
9909P104-1	9909 CONNECTOR GUARD
9909P301-1	9909 HEATER CONTROLLER
9909P103-1	9909 DOOR
ASI-GGLAS-2164	2164 GLASS OD 036 X ID 017
9909P105-1	9909 MID GUARD
99-EC-302	9909 POWER CONNECTOR HEADER